

| Technical Service Bulletin (TSB) - VR1J45GGRJY057489 | |
|---|---|
| C5CW011VQ0 : Version 1 of 05/08/2019 | Cancel and replace the document of 24/07/2019 |
| FOR : DS 7 CROSSBACK (X74) | |
| CUSTOMER SYMPTOM : | INFORMATION : THE FRONT DOOR WINDOWS DO NOT FULLY OPEN AND PROTRUDE BETWEEN 10 AND 15 MM FROM THE FRONT DOOR FRAME |
| CONDITIONS IN WHICH FAULT APPEARS : | WHEN OPENING THE FRONT DOOR WINDOWS IN SEQUENTIAL MODE |

1. ORIGIN

Product specification.

2. Service Action

None.

2.1. Repair

To open the front door windows fully, quickly press the "down" button on the front electric window control switches 4 consecutive times.

The operation conforms to specification ; Do not replace parts.

2.2. Repair time

No invoicing is to be applied for this bulletin.