

Technical Service Bulletin (TSB) - VR1J45GGRJY057489	
D6AW01ATQ0 : Version 0 of 12/11/2018	
FOR : DS 7 CROSSBACK (X74) UNTIL RPO 15313	
CUSTOMER SYMPTOM :	THE AMBIANCE LIGHTING OF THE DOOR PANELS CHANGES COLOUR AFTER UNLOCKING THE VEHICLE
CONDITIONS IN WHICH FAULT APPEARS :	ON UNLOCKING THE VEHICLE

1. ORIGIN

BSI (built-in systems interface) software.

2. Service Action

Downloading of the built-in systems interface.

2.1. Downloading

CAUTION : The diagnostic tool must be at the latest update version available on the remote update server

Download the latest built-in systems interface (BSI) software present on the aftersales server.

N.B. : Always configure the built-in systems interface after any download

2.2. Repair time

Invoicing time : 0,70H.

Operation code : 9R06RP00.

Cause code : 1204.

3. PRODUCTION SOLUTION

From RPO number 15314 : Modification of the built-in systems interface software.

N.B. : No longer complete a Dealer Issue Detection Incident (DID I) to report an incident that occurs on a vehicle manufactured within the range of application of this document, including vehicles manufactured before the production solution ; However, do send a Dealer Issue Detection for all cases of recurrence following application of this document or for all incidents occurring on a vehicle manufactured outside the range of application of this document, including after the production solution, in accordance with the Dealer Issue Detection relevancy standard (Incident or Assistance or Safety)